

General Environmental Incident Summary

Incident: 3391 **Date/Time Notice:** 7/18/2014 1600 **DEM Incident No:**

Responsible Party: Sanjel USA

Date Incident: 7/13/2014 **Time Incident:** 1500 **Duration:**

County: McKenzie **Twp:** 151 **Rng:** 97 **Sec:** 11 **Qtr:**

Lat: 47.91187 **Long:** -103.05910 **Method:** Interpolation from map

Location Description: Continental Resources - Rolfsrud 3-11H

Submitted By: Alan Heltemes

Affiliation: HSE Advisor

Address: 511 22nd Ave N.E

City: Williston

State: ND

Zip: 58801

Received By:

Contact Person: Alan Heltemes
511 22nd Ave N.E
Williston, ND 58801

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Hose failure

Description of Released Contaminant: Recirculated Fresh Water

Volume Spilled: 20.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

A suction hose failed

Risk Evaluation:

None

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

The Customer rep had an onsite vac truck clean up the spilled water

Wastes Disposal Location: Disposal well as per Customer directions

Agencies Involved:

Updates

Date: 7/18/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release occurred on an oilfield E&P facility location. NDIC has oversight.